AMENDMENT OF SOLICIT	ATION/MODIFI	CATION OF CONTRACT		1. CONTRACT	ID CODE		F PAGES
2. AMENDMENT/MODIFICATION NO.	3. EFFECTIVE DATE	4. REQUISITION/PURCHASE REQ. NO.			5. PROJECT	NO.(If appli	cable)
0004	22-Oct-2003	W81G67-3036-4923	W81G67-3036-4923				7
6. ISSUED BY CODE	W912ES	7. ADMINISTERED BY (If other than item 6))	COI	DE		
CONTRACTING DIVISION USACE - ST. PAUL 190 5TH STREET E ST. PAUL MN 55101		See Item 6					
8. NAME AND ADDRESS OF CONTRACTOR	(No., Street, County,	State and Zip Code)	ΧÍ	9A. AMENDM DACW37-03-B	ENT OF SO 3-0007	OLICITAT	ION NO.
			X S	9B. DATED (S 03-Sep-2003			
			1	10A. MOD. OF	CONTRAC	CT/ORDEF	₹ NO.
	1]	10B. DATED	(SEE ITEM	I 13)	
CODE	FACILITY COL	DE PPLIES TO AMENDMENTS OF SOLI	CIT	ATIONS			
X The above numbered solicitation is amended as set for					X is not exte	andad.	
Offer must acknowledge receipt of this amendment p (a) By completing Items 8 and 15, and returning or (c) By separate letter or telegram which includes a RECEIVED AT THE PLACE DESIGNATED FOR T REJECTION OF YOUR OFFER. If by virtue of this a provided each telegram or letter makes reference to the	copies of the amendment reference to the solicitation THE RECEIPT OF OFFERS mendment you desire to cha	nt; (b) By acknowledging receipt of this amendm n and amendment numbers. FAILURE OF YOU S PRIOR TO THE HOUR AND DATE SPECIFI ange an offer already submitted, such change ma	nent on JR AC IED M ıy be m	n each copy of the or CKNOWLEDGME MAY RESULT IN nade by telegram o	offer submitte NT TO BE	d;	
12. ACCOUNTING AND APPROPRIATION D	ATA (If required)						
) MODIFICATIONS OF CONTRACTS					
A. THIS CHANGE ORDER IS ISSUED PUR CONTRACT ORDER NO. IN ITEM 10A	SUANT TO: (Specify	T/ORDER NO. AS DESCRIBED IN IT y authority) THE CHANGES SET FOR			E MADE II	N THE	
B. THE ABOVE NUMBERED CONTRACT/ office, appropriation date, etc.) SET FOR C. THIS SUPPLEMENTAL AGREEMENT	TH IN ITEM 14, PUI	RSUANT TO THE AUTHORITY OF F			ch as chang	es in payin	g
D. OTHER (Specify type of modification an	d authority)						
E. IMPORTANT: Contractor is not,	is required to sig	gn this document and return	copi	es to the issuin	g office.		
14. DESCRIPTION OF AMENDMENT/MODIF where feasible.) The bid opening date remains unchanged. Bid Item numbers 10 and 12 are changed. Drawings and Specifications are changed.	ICATION (Organized	1 by UCF section headings, including so	olicita	ation/contract s	subject matt	er	
Except as provided herein, all terms and conditions of the control		n 9A or 10A, as heretofore changed, remains unc				e or print)	
	• /	TEL:		EMAIL:	\ JF	r	
15B. CONTRACTOR/OFFEROR	15C. DATE SIGNE		RICA		160	C. DATE S	SIGNED
		BY				2-Oct-200	13
(Signature of person authorized to sign)	-	(Signature of Contracting Of	fficer	:)	2	.2-061-200	J

SECTION SF 30 BLOCK 14 CONTINUATION PAGE

SUMMARY OF CHANGES

1. SECTION 00010 - SOLICITATION CONTRACT FORM

CLIN 0010 - SEGMENTAL BLOCK RETAINING WALL: Replace quantity of 7,052 square foot with 7,713 square foot.

CLIN 0012 - FLOODWALL: Replace quantity of 213 linear feet with 179 linear feet. Measurement indicates length of the T-wall. I-wall is to be included with pump station payment item.

A corrected bidding schedule reflecting these changes is included at the end of this amendment.

2. CHANGES TO SPECIFICATION SECTION 01000

- 1. Section 01000, General, Paragraph 3.5.9, Work in Vicinity of River Banks: Renumber the paragraph to 3.5.9.1 and delete the words "stockpile material or" from the paragraph.
- 2. Section 01000, General: Add a new paragraph 3.5.9 that reads as follows:
 - "3.5.9 Initiating Landslides from Material Stockpiles

The Contractor shall not permanently or temporarily stockpile excavated materials or construction materials riverward of the flood barrier alignment in order to avoid initiating a landslide. The following guidelines apply depending on the flood barrier type.

- a) Levee alignment material stockpiles shall not extend riverward of the levee alignment or to an elevation higher than the finished levee elevation. Material stockpiles shall either be located within the limits of the levee cross-section or further landward.
- b) Flood wall alignment material stockpiles shall not be placed riverward or within the footing limits of the wall. If materials are stockpiled landward of the wall footing, the stockpile height should not exceed the finished wall elevation.

Alternate lay down areas for material stockpiles must be approved by the Contracting Officers Representative."

3. CHANGES TO DRAWINGS

- 1. Drawing R-P-GF-64/1581, Profile 48" Detention Pond Outlet. The profile indicates 12" of R20 Riprap in the North Micropool. Riprap in the North Micropool shall be limited to that required for the RCP apron. Typical Detail for Riprap at RCP apron is shown on drawing R-P-GF-64/1733 (sheet 171). Riprap type shall be R20.
- 2. Drawing R-P-GF-64/1565, Coordinate E5 and Note 4. Delete reference to note 4 and delete note 4. Power poles will remain inplace. An MSE wall (Segmental Block Retaining Wall) shall be constructed around the power poles as shown in the attached sketches (MSE1, MSE2, and MSE3).
- 3. Drawing Number 64/1562: Coordinate E1. Add the following note to the drawing:
 - "6. Excavated materials from the floodwall, L8 gatewell, L8 pump station, outlet channel and storm sewer construction shall not be temporarily stockpiled riverward of the flood wall or levee

alignment in order to avoid initiating a landslide. All excavated materials shall be stockpiled landward of the wall footing to a height not to exceed the finished wall elevation, stockpiled within the limits of the levee cross-section or further landward, or transported to a lay down area approved by the C.O.R."

- 4. Drawing Number 64/1661, Coordinate G1: Add the following note to the drawing:
 - "2. Excavated materials from the floodwall, gated outlet L3, drop inlet structure, outlet channel and storm sewer construction shall not be temporarily stockpiled riverward of the flood wall alignment in order to avoid initiating a landslide. All excavated materials shall be stockpiled landward of the wall footing to a height not to exceed the finished wall elevation or transported to a lay down area approved by the C.O.R."
- 5. Drawing Number 64/1662, Coordinate G1: Add the following note to the drawing:
 - "4. Excavated materials from the flood wall and storm sewer construction shall not be temporarily stockpiled riverward of the flood wall alignment in order to avoid initiating a landslide. All excavated materials shall be stockpiled landward of the wall footing to a height not to exceed the finished wall elevation or transported to a lay down area approved by the C.O.R."

4. CLARIFICATION ON DRAWINGS

1. Note 3, drawing R-P-GF-64/1735. The sheetpile at station 214+68 is not an optional item by itself. Reach 2 work consists of 2 options. Option 2, Reach 2 is from station G205+00 to G214+74. Option 1, Reach 2 consists of the remainder of reach 2. Note 3 is intended to indicate that a provision for connecting the sheetpile between the option reaches is required in the event the all sheetpile cannot be driven at one time and some must be completed at a later date.

(End of Summary of Changes)

SECTION 00010 - Solicitation Contract Form

Basic Items:

ITEM NO 0001	SUPPLIES/SERVICES Bonds (Performance and Pa	QUANTITY 1 ayment)	UNIT Lump Sum	UNIT PRICE	AMOUNT
				·	·
ITEM NO 0002	SUPPLIES/SERVICES Preconstruction Damage Su	QUANTITY 1 nrvey	UNIT Lump Sum	UNIT PRICE	AMOUNT
				·	·
ITEM NO 0003	SUPPLIES/SERVICES Hydraulic Portable Operator	QUANTITY 1 or	UNIT Lump Sum	UNIT PRICE	AMOUNT
				·	·

Reach 1 From Sta F 120+12.88 To F 182+46.86

ITEM NO 0004	SUPPLIES/SERVICES Demolition	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0005	SUPPLIES/SERVICES Clearing and Grubbing	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0006	SUPPLIES/SERVICES Stripping	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT

ITEM NO 0007	SUPPLIES/SERVICES Levee Toe Ditch Excavation	QUANTITY	UNIT	UNIT PRICE	AMOUNT
ITEM NO 0007AA	SUPPLIES/SERVICES First 450 CY	QUANTITY 450	UNIT Cubic Yard	UNIT PRICE	AMOUNT
ITEM NO 0007AB	SUPPLIES/SERVICES Over 450 CY	QUANTITY 110	UNIT Cubic Yard	UNIT PRICE	AMOUNT .
ITEM NO 0008	SUPPLIES/SERVICES Select Impervious Fill	QUANTITY	UNIT	UNIT PRICE	AMOUNT
ITEM NO 0008AA	SUPPLIES/SERVICES First 13,500 Cubic Yards	QUANTITY 13,500	UNIT Cubic Yard	UNIT PRICE	AMOUNT
ITEM NO 0008AB	SUPPLIES/SERVICES Over 13,500 Cubic Yards	QUANTITY 5,830	UNIT Cubic Yard	UNIT PRICE	AMOUNT
ITEM NO 0009	SUPPLIES/SERVICES Impervious Fill	QUANTITY	UNIT	UNIT PRICE	AMOUNT

ITEM NO 0009AA	SUPPLIES/SERVICES First 355,000 Cubic Yards	QUANTITY 355,000	UNIT Cubic Yard	UNIT PRICE	AMOUNT
	1130 222,000 2422 1444	-			
ITEM NO 0009AB	SUPPLIES/SERVICES	QUANTITY 135,000	UNIT Cubic Yard	UNIT PRICE	AMOUNT
	Over 355,000 Cubic Yard	s		·	
ITEM NO 0010	SUPPLIES/SERVICES	QUANTITY 7,713	UNIT Square Foot	UNIT PRICE	AMOUNT
	Segmental Block Retaining	g Wall	Poot		
ITEM NO 0011	SUPPLIES/SERVICES	QUANTITY 5,930	UNIT Linear	UNIT PRICE	AMOUNT
	Inspection Trench		Foot		
ITEM NO 0012	SUPPLIES/SERVICES	QUANTITY 179	UNIT Linear	UNIT PRICE	AMOUNT
	Floodwall		Foot		
ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
0013	L9 Gated Outlet	1	Lump Sum		
ITEM NO 0014	SUPPLIES/SERVICES	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
	L9 Sluice Gate				

ITEM NO 0015	SUPPLIES/SERVICES L9 Detention Pond	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0016	SUPPLIES/SERVICES L9 Storm Sewer Collector S	QUANTITY 1 System	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0017	SUPPLIES/SERVICES L10 Gated Outlet	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0018	SUPPLIES/SERVICES L10 Sluice Gate	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0019	SUPPLIES/SERVICES L10 Access Road	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0020	SUPPLIES/SERVICES L10 Preformed Scour Hole	QUANTITY 1 and Channel	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0021	SUPPLIES/SERVICES 13th Ave Storm Sewer Syst	QUANTITY 1 em	UNIT Lump Sum	UNIT PRICE	AMOUNT

ITEM NO 0022	SUPPLIES/SERVICES Bituminous Trail	QUANTITY 4,210	UNIT Square Yard	UNIT PRICE	AMOUNT
ITEM NO 0023	SUPPLIES/SERVICES Park Benches	QUANTITY 2	UNIT Each	UNIT PRICE	AMOUNT
ITEM NO 0024	SUPPLIES/SERVICES Topsoil and Seeding, Class	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT .
ITEM NO 0025	SUPPLIES/SERVICES Topsoil and Seeding, Class	QUANTITY 1 2	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0026	SUPPLIES/SERVICES Topsoil and Seeding, Class	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0027	SUPPLIES/SERVICES Topsoil and Seeding, Class	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT .
ITEM NO 0028	SUPPLIES/SERVICES Trees and Shrubs	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT

Reach 1: Pump Station L8

ITEM NO 0029	SUPPLIES/SERVICES QUANTITY 1 L8 Pump Station Strucutre and Gatewell	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0030	SUPPLIES/SERVICES QUANTITY 1 L8 Pump Station and Gatewell Sluice Gates	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0031	SUPPLIES/SERVICES QUANTITY 1 L8 Mechanical	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0032	SUPPLIES/SERVICES QUANTITY 1 L8 Electrical	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0033	SUPPLIES/SERVICES QUANTITY 1 L8 Electrical Service by City	UNIT Lump Sum	UNIT PRICE 80,204.79	AMOUNT 80,204.79
ITEM NO 0034	SUPPLIES/SERVICES QUANTITY 1 L8 Electrical Service by Contractor	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0035	SUPPLIES/SERVICES QUANTITY 1 L8 Install Engine Generator Set	UNIT Lump Sum	UNIT PRICE	AMOUNT

DACW37-03-B-0007 0004 Page 10 of 21

ITEM NO 0036	SUPPLIES/SERVICES L8 Furnish and Install Load	QUANTITY 1 d Bank	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0037	SUPPLIES/SERVICES L8 Preformed Scour Hole	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0038	SUPPLIES/SERVICES L8 Storm Sewer Collector	QUANTITY 1 System	UNIT Lump Sum	UNIT PRICE	AMOUNT
					·-

Total Price for Basic Items 0001 through 0038:_____

Option 1:

Reach 2 – Sta 167+90 to G 205+00 and Sta G214+74 to G 233+50

ITEM NO 0039 OPTION	SUPPLIES/SERVICES Bonds for Option 1 (Perfor Payment)	QUANTITY 1 rmance and	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0040 OPTION	SUPPLIES/SERVICES Demolition	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0041 OPTION	SUPPLIES/SERVICES Clearing and Grubbing	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0042 OPTION	SUPPLIES/SERVICES Stripping	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0043 OPTION	SUPPLIES/SERVICES Levee Toe Ditch Excavation	QUANTITY	UNIT	UNIT PRICE	AMOUNT
ITEM NO 0043AA OPTION	SUPPLIES/SERVICES First 1860 CY	QUANTITY 1,860	UNIT Cubic Yard	UNIT PRICE	AMOUNT

ITEM NO 0043AB	SUPPLIES/SERVICES	QUANTITY 800	UNIT Cubic Yard	UNIT PRICE	AMOUNT
OPTION	Over 1860 CY				
ITEM NO 0044	SUPPLIES/SERVICES	QUANTITY 1,670	UNIT Cubic Yard	UNIT PRICE	AMOUNT
OPTION	Levee Removal		14.0		
ITEM NO 0045 OPTION	SUPPLIES/SERVICES Select Impervious Fill	QUANTITY	UNIT	UNIT PRICE	AMOUNT
ITEM NO 0045AA	SUPPLIES/SERVICES	QUANTITY 8,475	UNIT Cubic Yard	UNIT PRICE	AMOUNT
OPTION	First 8475 C Y			·	
ITEM NO 0045AB	SUPPLIES/SERVICES	QUANTITY 3,630	UNIT Cubic Yard	UNIT PRICE	AMOUNT
OPTION	Over 8475 CY			·	·
ITEM NO 0046 OPTION	SUPPLIES/SERVICES Impervious Fill	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	-				
ITEM NO 0046AA	SUPPLIES/SERVICES	QUANTITY 39,050	UNIT Cubic Yard	UNIT PRICE	AMOUNT
OPTION	First 39,050 CY				
					·-

ITEM NO 0046AB	SUPPLIES/SERVICES	QUANTITY 16,735	UNIT Cubic Yard	UNIT PRICE	AMOUNT
OPTION	Over 39,050 CY		Tulu .		
ITEM NO 0047 OPTION	SUPPLIES/SERVICES Inspection Trench	QUANTITY 3,714	UNIT Linear Foot	UNIT PRICE	AMOUNT
ITEM NO 0048 OPTION	SUPPLIES/SERVICES Floodwall	QUANTITY 1,883	UNIT Linear Foot	UNIT PRICE	AMOUNT
ITEM NO 0049 OPTION	SUPPLIES/SERVICES L3 Gated Outlet	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0050 OPTION	SUPPLIES/SERVICES L3 Gated Outlet Sluice Gate	QUANTITY 1	UNIT Lump Sum	UNIT PRICE 	AMOUNT
ITEM NO 0051 OPTION	SUPPLIES/SERVICES L3 Preformed Scour Hole an	QUANTITY 1 d Channel	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0052 OPTION	SUPPLIES/SERVICES L3 Storm Sewer Collector S	QUANTITY 1 ystem	UNIT Lump Sum	UNIT PRICE	AMOUNT

ITEM NO 0053 OPTION	SUPPLIES/SERVICES QUANTIT 1 L3 Concrete Drive	Y UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0054 OPTION	SUPPLIES/SERVICES QUANTIT 1 L3 Electrical Service by City	Y UNIT Lump Sum	UNIT PRICE	AMOUNT
			26,982.84	26,982.84
ITEM NO 0055 OPTION	SUPPLIES/SERVICES QUANTIT 1 L3 Electrical Service by Contractor	Y UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0056 OPTION	SUPPLIES/SERVICES QUANTIT 1 L3 Electrical	Y UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0057 OPTION	SUPPLIES/SERVICES QUANTIT I Maintenance Road Raise	Y UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0058 OPTION	SUPPLIES/SERVICES QUANTIT 3,811 Bituminous Trail	Y UNIT Square Yard	UNIT PRICE	AMOUNT
ITEM NO 0059 OPTION	SUPPLIES/SERVICES QUANTIT 1 Topsoil and Seeding, Class 1	Y UNIT Lump Sum	UNIT PRICE	AMOUNT

ITEM NO 0060 OPTION	SUPPLIES/SERVICES Topsoil and Seeding, Class	QUANTITY 1 2	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0061 OPTION	SUPPLIES/SERVICES Topsoil and Seeding, Class	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0062 OPTION	SUPPLIES/SERVICES Topsoil and Seeding, Class	QUANTITY 1 4	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0063 OPTION	SUPPLIES/SERVICES Trees and Shrubs	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
Rea	ch 2: Pump Station	1.6			
ITEM NO 0064 OPTION	SUPPLIES/SERVICES L6 Pump Station Structure	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0065 OPTION	SUPPLIES/SERVICES L6 Pump Station Sluice Gat	QUANTITY 1 te	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0066 OPTION	SUPPLIES/SERVICES L6 Gatewell	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT

ITEM NO 0067 OPTION	SUPPLIES/SERVICES QU L6 Gatewell Sluice Gate	JANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT .
ITEM NO 0068 OPTION	SUPPLIES/SERVICES QU L6 Access Road	JANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0069 OPTION	SUPPLIES/SERVICES QU L6 Mechanical	JANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0070 OPTION	SUPPLIES/SERVICES QU L6 Electrical	JANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0071 OPTION	SUPPLIES/SERVICES QU L6 Electrical Service by City	JANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
				403,756.63	403,756.63
ITEM NO 0072 OPTION	SUPPLIES/SERVICES QU L6 Electrical Service by Contract	JANTITY 1 actor	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0073 OPTION	SUPPLIES/SERVICES QU L6 Install Engine Generator Set	JANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0074 OPTION	SUPPLIES/SERVICES QU L6 Furnish and Install Load Bar	JANTITY 1 nk	UNIT Lump Sum	UNIT PRICE	AMOUNT
			-	·	

DACW37-03-B-0007 0004 Page 17 of 21

ITEM NO 0075 OPTION	SUPPLIES/SERVICES L6 Prefomed Scour Hole a	QUANTITY 1 and Channel	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0076	SUPPLIES/SERVICES	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
OPTION	L6 Detention Pond		•		
					·
ITEM NO 0077	SUPPLIES/SERVICES	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
OPTION	L6 Storm Sewer Collector	System	F ~		
					·

Total Price for Option 1 Items 0039 through 0077:_____

Option 2:


Reach 2 – Sta. G205+00 to G214+74

ITEM NO 0078 OPTION	SUPPLIES/SERVICES Bonds for Option II (Perfor Payment)	QUANTITY 1 rmance and	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0079 OPTION	SUPPLIES/SERVICES Preconstruction Damage Su	QUANTITY 1 urvey	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0080 OPTION	SUPPLIES/SERVICES Demolition	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0081 OPTION	SUPPLIES/SERVICES Clearing and Grubbing	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0082 OPTION	SUPPLIES/SERVICES Stripping	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0083 OPTION	SUPPLIES/SERVICES Select Impervious Fill	QUANTITY	UNIT	UNIT PRICE	AMOUNT


ITEM NO 0083AA	SUPPLIES/SERVICES	QUANTITY 2,385	UNIT Cubic Yard	UNIT PRICE	AMOUNT
OPTION	First 2385 CY		Taiu		
					·
ITEM NO 0083AB	SUPPLIES/SERVICES	QUANTITY 1,025	UNIT Cubic Yard	UNIT PRICE	AMOUNT
OPTION	Over 2385 CY		Taiu		
					·
ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
0084 OPTION	Impervious Fill				
ITEM NO 0084AA	SUPPLIES/SERVICES	QUANTITY 7,250	UNIT Cubic	UNIT PRICE	AMOUNT
OPTION	First 7250 CY		Yard		
					·
ITEM NO 0084AB	SUPPLIES/SERVICES	QUANTITY 3,110	UNIT Cubic	UNIT PRICE	AMOUNT
OPTION	Over 7250 CY		Yard		
ITEM NO 0085	SUPPLIES/SERVICES	QUANTITY 974	UNIT Linear Foot	UNIT PRICE	AMOUNT
OPTION	Inspection Trench		1 001		
					·
ITEM NO 0086	SUPPLIES/SERVICES	QUANTITY 475	UNIT Square Foot	UNIT PRICE	AMOUNT
OPTION	Segmental Block Retaining	g Wall	1001		
				·	·


ITEM NO 0087 OPTION	SUPPLIES/SERVICES Bituminous Trail	QUANTITY 2,480	UNIT Square Yard	UNIT PRICE	AMOUNT
ITEM NO 0088 OPTION	SUPPLIES/SERVICES Bituminous Trail Handrail	QUANTITY 290	UNIT Linear Foot	UNIT PRICE	AMOUNT
ITEM NO 0089 OPTION	SUPPLIES/SERVICES Topsoil and Seeding, Class 1	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0090 OPTION	SUPPLIES/SERVICES Topsoil and Seeding, Class 2	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0091 OPTION	SUPPLIES/SERVICES Topsoil and Seeding, Class 3	QUANTITY 1 3	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0092 OPTION	SUPPLIES/SERVICES Topsoil and Seeding, Class 4	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT
ITEM NO 0093 OPTION	SUPPLIES/SERVICES Trees and Shrubs	QUANTITY 1	UNIT Lump Sum	UNIT PRICE	AMOUNT

Total Price for Option 2 Items 0078 through 0093:	
Total Price for All Items 0001 through 0093:	



MSE1





PROFILE (NTS)
MSE WALL - STA. F 163+55 TO F 164+25